









5.2.1 Patio condition

UNDERMINED

Further review/ Monitor

The patio surface was observed to be undermined by soil erosion. We recommend that the patio be repaired as required to present-day industry trade standards for the safe use of affected areas.

Recommendation
Contact a qualified professional.

